
# H TECHNICAL PROCEDURE INTRAAX® SUSPENSIONS WITH UBL

SUBJECT: Caging Tool Access To Brake Chambers

LIT NO: T82002 DATE: June 2014

## **REMOVING THE LIFT ACTUATOR MOUNTING PLATE ASSEMBLY**

The following steps describe removal of the lift actuator mounting plate assembly to gain access to the brake chamber. The procedure is the same for all brake chambers, regardless of chamber manufacturer (including chambers with integral caging tool).




**NOTE:** Shown is AANT, but the procedure is similar on other INTRAAX suspensions with UBL.

**Step 2:** Using <sup>3</sup>/<sub>4</sub>" wrenches, remove inboard lift actuator mounting plate assembly bolt and nut.



**Step 1:** Suspension lowered and air exhausted from lift actuators.



**Step 3:** Remove outboard lift actuator mounting plate bolt and nut.





Step 4: Push bracket assembly and lift actuator downward. Step 5: Remove caging tool access plug. **NOTE:** Lift actuator remains attached to the mounting plate.



Step 6: Insert caging tool as shown. Tool may need to be inserted at an angle in order to fit into slot.



Step 8: Tighten caging tool until spring is compressed and brakes are released.





Step 7: Using 34" wrench, run caging tool nut snug against chamber housing. Continue turning to compress spring.



End of procedure: Brake chamber shown fully caged.



### Call your trailer dealer or Hendrickson at 866.RIDEAIR (743.3247) for additional information.



www.hendrickson-intl.com

#### TRAILER COMMERCIAL VEHICLE SYSTEMS 2070 Industrial Place SE Canton, OH 44707-2641 USA 866.RIDEAIR (743.3247) 330.489.0045 • Fax 800.696.4416

Hendrickson Canada 250 Chrysler Drive, Unit #3 Brampton, ON Canada L6S 6B6 800.668.5360 905.789.1030 • Fax 905.789.1033

#### **Hendrickson Mexicana**

Circuito El Marqués Sur #29 Parque Industrial El Marqués Pob. El Colorado, Municipio El Marqués, Querétaro, México C.P. 76246 +52 (442) 296.3600 • Fax +52 (442) 296.3601

T82002 06-14 ECN 22124

Information contained in this literature was accurate at the time of publication. Product changes may have been made after the copyright date that are not reflected. © 2014 Hendrickson USA, L.L.C. All Rights Reserved