



July 14, 2016

**Attention:**

**Engineering Managers  
Purchasing Managers  
Production Managers  
Quality Managers  
Service Managers  
Parts Managers**

(Please copy to other concerned departments)

**Please see attached document!**

**Product Update:**

**DRUM BRAKE CHAMBERS AND SLACK  
UPDATE**

# **PRODUCT UPDATE**

## **DRUM BRAKE CHAMBERS AND SLACK UPDATE**

**LIT NO: P76023**

**DATE: July 2016**

Hendrickson Trailer Commercial Vehicle Systems announces several changes to drum brake chambers and slack adjuster offerings.

### **NEW BRAKE CHAMBER OPTION**

Hendrickson is pleased to announce the addition WABCO TRISTOP™ D actuators to its drum brake product offerings. The double diaphragm spring brake features WABCO's patented Internal Breathing Valve (IBV) technology and is backed by a WABCO 7-year parts warranty in On-Highway applications. Effective immediately, the WABCO TRISTOP D Type 30/30 brake actuators are available on all INTRAAX®, VANTRAAX® and ULTRAA-K® integrated air suspension systems.

To receive a valid part number, price and availability for new suspensions equipped with WABCO brake chambers, please submit a completed ordering guide to your sales or customer service representative. Models that are currently configured with other brake chamber options will require new part numbers. Visit [www.hendrickson-intl.com](http://www.hendrickson-intl.com) to learn more about Ready-To-Roll® packages or to obtain the latest revisions of the ordering guides.



### **6" SLACK RESTRICTION**

Hendrickson is updating its product offerings to reflect slack adjuster and brake chamber compatibility. Effective for shipments in October 2016, Hendrickson will require that when specifying a 6" slack adjuster and a Type 30/30 or Type 19/19 brake chamber, the brake chamber must be 3.0" long stroke.

Models that are currently equipped with the combination of 6" slacks and standard 2.5" stroke chambers will be changed and will require new part numbers. Options will include either changing to a 5.5" slack adjuster or changing to a 3.0" long stroke chamber. Please contact your sales or customer service representative to assist with this process.

**Please note:** there are no restrictions when specifying 5.5" slack adjuster in combination with current brake chambers.

### **ORDERING GUIDE UPDATE**

Hendrickson is updating the product ordering guides to enhance and simplify the selection of available brake chamber and slack combinations. Visit [www.hendrickson-intl.com](http://www.hendrickson-intl.com) to obtain the latest revisions of the ordering guides.

As always, Hendrickson is committed to providing world-class quality products and exceptional customer service. For more information call 1-866-RIDEAIR (743-3247) to speak with your customer service representative.

*Call Hendrickson at 330.489.0045 or 866.RIDEAIR (743.3247) for additional information.*



[www.hendrickson-intl.com](http://www.hendrickson-intl.com)

#### **TRAILER COMMERCIAL VEHICLE SYSTEMS**

2070 Industrial Place SE  
Canton, OH 44707-2641 USA  
866.RIDEAIR (743.3247)  
330.489.0045 • Fax 800.696.4416

#### **Hendrickson Canada**

250 Chrysler Drive, Unit #3  
Brampton, ON Canada L6S 6B6  
800.668.5360  
905.789.1030 • Fax 905.789.1033

#### **Hendrickson Mexicana**

Circuito El Marqués Sur #29  
Parque Industrial El Marqués  
Pob. El Colorado, Municipio El Marqués,  
Querétaro, México C.P. 76246  
+52 (442) 296.3600 • Fax +52 (442) 296.3601