

TIREMAAX® CP TIRE INFLATION SYSTEM

This unit is equipped with the TIREMAAX® CP tire inflation system.

If the lamp remains on continuously for more than 10 minutes, one or more tires may be low or the system requires service.

For complete service details, refer to Hendrickson publication L995 *TIREMAAX CP Installation, Service and Troubleshooting Procedures* or call the Hendrickson technical service department in the United States and Canada at 866-743-3247.

Trailer Commercial Vehicle Systems
2070 Industrial Place SE
Canton, OH 44707-2641 USA
866.RIDEAIR (743.3247)
330.489.0045
FAX 800.696.4416



www.hendrickson-intl.com

Hendrickson Canada
250 Chrysler Drive, Unit #3
Brampton, ON Canada L6S 6B6
905.789.1030
FAX 905.789.1033