

# TIREMAAX® TIRE INFLATION SYSTEM

This unit is equipped with the TIREMAAX®  
tire inflation system.

If the lamp remains on continuously for more  
than 10 minutes, one or more tires may be low  
or the system requires service.

In the event of a substantial system leak, set the trailer  
park brakes, then close controller supply valve.

For complete service details, refer to Hendrickson publication  
T51002 *TIREMAAX Installation, Service and Troubleshooting Procedures*,  
or call the Hendrickson Technical Services Department in the  
United States and Canada at 866-RIDEAIR (743-3247).

**Trailer Commercial Vehicle Systems**  
2070 Industrial Place SE  
Canton, OH 44707-2641 USA  
866.RIDEAIR (743.3247)  
330.489.0045  
FAX 800.696.4416



[www.hendrickson-intl.com](http://www.hendrickson-intl.com)

**Hendrickson Canada**  
250 Chrysler Drive, Unit #3  
Brampton, ON Canada L6S 6B6  
905.789.1030  
FAX 905.789.1033