

LIT NO: L1155 DATE: December 2010

Revision: A

Hendrickson Trailer Suspension Systems will be superseding the S-21784 (AAT 25K), S-27341 (AAT 30K) and S-24443 (HKA 50K) air springs to the S-20901, S-25873 and S-23748 air springs respectively, beginning April 2010.

Currently all three aftermarket replacement air spring kits (S-21784, S-27341, S-24443) include the air spring and a steel air spring disk (B-21786). The B-21786 steel air spring disk is included on the original equipment suspension and can be re-used when replacing the air spring. Therefore, the steel disk will no longer be included in the aftermarket kit.



Please note the B-21786 steel air spring disk is **still required** when replacing the air spring if originally equipped with the disc. As previously stated, you can re-use the steel disk from the air spring being replaced. If a new steel air spring disk is required please order the aftermarket equivalent, part number S-21786. Please refer to the chart below for further clarification.

Air Springs with weld-on Steel Pedestals ¹	Current Aftermarket Air Spring Kit	New Aftermarket Air Spring	Steel Air Spring Disk
INTRAAX®			
AAT 25K	S-21784 (includes C-20901, B-21786)	S-20901	S-21786
AAT 30K	S-27341 (includes C-25873, B-21786)	S-25873	S-21786
VANTRAAX®			
HKA 50K	S-24443 (includes C-23748, B-21786)	S-23748	S-21786

1. AAT suspensions with bolt-on pedestals do not require the steel air spring disc. Reference T19001 (Wide Pivot LDA Axle Component Changes).

For additional information, call 1-866-RIDEAIR (743-3247) or visit www.hendrickson-intl.com.

Call Hendrickson at 866.RIDEAIR (743.3247) for additional information.



TRAILER COMMERCIAL VEHICLE SYSTEMS 2070 Industrial Place SE Canton, OH 44707-2641 USA 866.RIDEAIR (743.3247) 330.489.0045 • Fax 800.696.4416 Hendrickson Canada 250 Chrysler Drive, Unit #3 Brampton, ON Canada L6S 6B6 800.668.5360 905.789.1030 • Fax 905.789.1033 Hendrickson Mexicana

Circuito El Marqués Sur #29 Parque Industrial El Marqués Pob. El Colorado, Municipio El Marqués, Querétaro, México C.P. 76246 +52 (442) 296.3600 • Fax +52 (442) 296.3601

www.hendrickson-intl.com

L1 155 12-10 ECN 25373 Information contained in this literature was accurate at the time of publication. Product changes may have been made after the copyright date that are not reflected. © 2010 Hendrickson USA, LLC. All Rights Reserved