


PRODUCT UPDATE

WHEEL-END LUBRICANT OPTIONS

LIT NO: P76038

DATE: June 2021

Hendrickson Trailer Commercial Vehicle Systems announces a change to semi-fluid lubricant options available in all Ready-To-Roll® wheel-end packages on INTRAAX®, VANTRAAX®, ULTRAA-K®, INTRAAX SP, CONNEX® and CONNEX-ST® suspensions and TRLAXLE® non-integrated axles.



Effective immediately, Hendrickson semi-fluid grease will replace the option for Chevron Delo SF semi-fluid grease for standard 1-year, HXL3®, HXL5® or HXL7® wheel-end assemblies. This synthetic semi-fluid grease is formulated to meet Hendrickson's stringent standards and fulfills the performance requirements for the North American trailer market.

Suspension and/or axle model numbers and wheel-end warranties are not affected by this change. Users may notice a different in color between the two lubricants when performing maintenance and are encouraged to contact Hendrickson prior to servicing Hendrickson Extended-Life (HXL) wheel-ends.

Per TMC Recommended Practices and Hendrickson maintenance procedures, wheel-end lubricants should not be mixed. During maintenance, the hub and bearings should be cleaned and inspected prior to reassembly. Refer to L496 *Wheel-End Maintenance Procedures*, T72007 *HXL5 Wheel-End Maintenance Procedures* or T72002 *HXL7 Wheel-End Maintenance Procedures* for more detailed information on proper maintenance procedures.

As always, Hendrickson is committed to providing world-class products and customer service. Please contact your Hendrickson sales representative or call 1-866-RIDEAIR (743-3247) to speak with a customer service representative regarding this change. Visit <http://www.hendrickson-intl.com> for more information and links to the maintenance literature.

Actual product performance may vary depending upon vehicle configuration, operation, service and other factors.

All applications must comply with applicable Hendrickson specifications and must be approved by the respective vehicle manufacturer with the vehicle in its original, as-built configuration. Contact Hendrickson for additional details regarding specifications, applications, capacities, and operation, service and maintenance instructions.

Call Hendrickson at 330.489.0045 or 866.RIDEAIR (743.3247) for additional information.



www.hendrickson-intl.com

TRAILER COMMERCIAL VEHICLE SYSTEMS
2070 Industrial Place SE
Canton, OH 44707-2641 USA
866.RIDEAIR (743.3247)
330.489.0045 • Fax 800.696.4416

Hendrickson Canada
250 Chrysler Drive, Unit #3
Brampton, ON Canada L6S 6B6
800.668.5360
905.789.1030 • Fax 905.789.1033

Hendrickson Mexicana
Circuito El Marqués Sur #29
Parque Industrial El Marqués
Pob. El Colorado, Municipio El Marqués,
Querétaro, México C.P. 76246
+52 (442) 296.3600 • Fax +52 (442) 296.3601