H TECHNICAL PROCEDURE SURELOK® INSPECTION

SUBJECT: SURELOK - Restraining Bolt Prior to 2015

LIT NO: T89010 DATE: February 2021

REVISION:

INSPECTING THE RESTRAINING BOLT

Inspect for the presence of the restraining bolt on suspensions prior to 2015, with the SURELOK actuator centered in the rear crossmember. The restraining bolt limits the rearward travel of the SURELOK arm assembly. A missing restraining bolt will allow for the actuator to overextend causing damage to the actuator. If the restraining bolt is not present, use the "INSTALLING THE RESTRAINING BOLT" procedure listed below.



INSTALLING THE RESTRAINING BOLT

- 1. Slip the 3/8-in. hardened flat washer onto the $3/8 \times 6$ -in. bolt.
- 2. Insert the bolt and washer assembly through the hole in the actuator bracket and the hole in the rear cross member.
- 3. Thread the flanged nut on the bolt and tighten only until two threads of the bolt are visible past the nut.

Call Hendrickson at 866.RIDEAIR (743.3247) for additional information.



TRAILER COMMERCIAL VEHICLE SYSTEMS 2070 Industrial Place SE Canton, OH 44707-2641 USA 866.RIDEAIR (743.3247) 330.489.0045 • Fax 800.696.4416 Hendrickson Canada 250 Chrysler Drive, Unit #3 Brampton, ON Canada L65 6B6 800.668.5360 905.789.1030 • Fax 905.789.1033 Hendrickson Mexicana

Circuito El Marqués Sur #29 Parque Industrial El Marqués Pob. El Colorado, Municipio El Marqués, Querétaro, México C.P. 76246 +52 (442) 296.3600 • Fax +52 (442) 296.3601

www.hendrickson-intl.com