

HXL7[®] HENDRICKSON EXTENDED-LIFE 7-YEAR SYSTEM[™] WHEEL END

- * **DO NOT remove the HXL7[®] hubcap without first contacting Hendrickson Trailer Technical Services Department in the United States and Canada at 866-RIDEAIR (743-3247).**
- **HXL7 is equipped with a PRECISION320[™] nut system.**
- **Do not add lubricant, hub is pre-filled with Chevron Delo[®] SF grease.**
- **Quarterly rotate wheel end to ensure smooth and quiet rotation (T72002). If not smooth and quiet rotation, contact Hendrickson.***
- **Monthly visually inspect hubcap and back of hub for evidence of lube leaks.**

NOTE: Wheel-end repairs performed prior to contacting Hendrickson Technical Services voids the warranty. Refer to L583 for details.

Trailer Commercial Vehicle Systems
2070 Industrial Place SE
Canton, OH 44707-2641 USA
866.RIDEAIR (743.3247)
330.489.0045
FAX 800.696.4416



www.hendrickson-intl.com

Hendrickson Canada
250 Chrysler Drive, Unit #3
Brampton, ON Canada L6S 6B6
905.789.1030
FAX 905.789.1033