

HENDRICKSON EXTENDED-LIFE 5-YEAR SYSTEM™ (HXL5™) WHEEL END

- * **DO NOT** remove the HXL5™ hubcap without first contacting Hendrickson Technical Services Department in the United States at 866-RIDEAIR (743-3247) or in Canada at 800-668-5360.
- HXL5™ is equipped with a PRECISION320™ nut system on a HP spindle or a PRECISION240™ nut system on a HN spindle.
- Do not add lubricant, hub is pre-filled with Chevron Delo SF grease.
- Quarterly rotate wheel end to ensure smooth, quiet rotation (T72007). If not, contact Hendrickson. *
- Monthly visually inspect hubcap and back of hub for evidence of lube leaks.

NOTE: Wheel-end repairs performed prior to contacting Hendrickson Technical Services voids the warranty. Refer to L583 for details.

Trailer Commercial Vehicle Systems
2070 Industrial Place SE
Canton, OH 44707-2641 USA
866.RIDEAIR (743.3247)
330.489.0045
FAX 800.698.4416



www.hendrickson-intl.com

Hendrickson Canada
250 Chrysler Drive, Unit #3
Brampton, OH Canada L6S 6B6
905.789.1030
FAX 905.789.1033

T70005 07-12 ECN 21213

©2012 Hendrickson USA, L.L.C. All Rights Reserved

Printed in United States of America