
HPARTS LIST

SBL[®] SIDE BEAM LIFT™


LIT NO: L1327

DATE: December 2020









ITEM	DESCRIPTION	PART NO.	QTY	NOTE
1	AIR SPRING	S-23114	2	
2	LIFT ASSEMBLY BOLT AND CHAIN KIT	A-31934-1	1	Contains 2 sets of chains and hardware
3	FRAME BRACKET LIFT SUPPORT			
		B-31918-1	1	
		B-31918-2	1	
4	ARM LIFT SUPPORT	C-31399	2	
5	FRONT BRACKET LIFT SUPPORT			
		C-31915-1	1	
		C-31915-2	1	
				•

Actual product performance may vary depending upon vehicle configuration, operation, service and other factors.

All applications must comply with applicable Hendrickson specifications and must be approved by the respective vehicle manufacturer with the vehicle in its original, as-built configuration.

Contact Hendrickson for additional details regarding specifications, applications, capacities, and operation, service and maintenance instructions.

Call Hendrickson at 330.489.0045 or 866.RIDEAIR (743.3247) for additional information.

HENDRICKSON

www.hendrickson-intl.com

TRAILER COMMERCIAL VEHICLE SYSTEMS

2070 Industrial Place SE Canton, OH 44707-2641 USA 866.RIDEAIR (743.3247) 330.489.0045 • Fax 800.696.4416 **Hendrickson Canada** 250 Chrysler Drive, Unit #3 Brampton, ON Canada L6S 6B6

800.668.5360 905.789.1030 • Fax 905.789.1033 Hendrickson Mexicana

Circuito El Marqués Sur #29
Parque Industrial El Marqués
Pob. El Colorado, Municipio El Marqués,
Querétaro, México C.P. 76246
+52 (442) 296.3600 • Fax +52 (442) 296.3601