

HXL3® HENDRICKSON EXTENDED-LIFE 3-YEAR SYSTEM™ WHEEL END

- * **DO NOT remove the HXL3® hubcap without first contacting Hendrickson Trailer Technical Services Department in the United States and Canada at 866-RIDEAIR (743-3247).**
- **HXL3® is equipped with PRECISION320™ nut system on a HP spindle or PRECISION240™ nut system on a HN spindle.**
- **Per end user specifications, hubs are pre-filled with SAE 75W-90 synthetic gear lubricant or SAE 80W / 90W gear oil. DO NOT MIX.**
- **Quarterly rotate wheel end to ensure smooth and quiet rotation (T72006). If not smooth and quiet rotation, contact Hendrickson.***
- **Monthly visually inspect hubcap and back of hub for evidence of lube leaks.**

NOTE: Wheel-end repairs performed prior to contacting Hendrickson Technical Services voids the warranty. Refer to L583 for details.

Trailer Commercial Vehicle Systems
2070 Industrial Place SE
Canton, OH 44707-2641 USA
866.RIDEAIR (743.3247)
330.489.0045
FAX 800.696.4416



www.hendrickson-intl.com

Hendrickson Canada
250 Chrysler Drive, Unit #3
Brampton, ON Canada L6S 6B6
905.789.1030
FAX 905.789.1033