

SUBJECT: Important Warranty and Maintenance Information LIT NO: T79002 DATE: October 2015

This bulletin is a reminder to second hand, or subsequent, trailer owners who have purchased a used trailer equipped with HUS wheel-end hub assemblies. Regarding HUS wheel-end hub assembly, Hendrickson provides warranty coverage for 7 years Parts and Labor from the original date in service. The warranty coverage is not limited to only the original owner.

Hendrickson publication number <u>L583</u> *Comprehensive Warranty Statement* describes how to contact Hendrickson Trailer Technical Services (page 2) regarding warranty claim and coverage considerations, coverage details and labor allowances. <u>L583</u> is located on Hendrickson's Trailer Literature website on-line at:

## www.hendrickson-intl.com/L583

Owners and service/maintenance providers must contact Hendrickson prior to any to potential warranty repair to review possible warranty coverage, proper repair procedures or any potential other assistance.

Please remember, the HUS wheel-end hub assembly does require periodic maintenance:

- **Quarterly** Raise the wheel-end and rotate to realize smooth and quiet rotation. (If smooth and quiet is not realized, please contact Hendrickson.)
- **Every 2 weeks** If equipped with a Wheel-End Monitor (WEM<sup>™</sup>), check bearing condition by holding a magnet to the WEM. A blinking LED indicates bearing condition:

GREEN — Bearings operating properly RED — Damage detected RED and GREEN — WEM malfunction

For more details, refer to Hendrickson technical publication number <u>L775 Rev A HUS Wheel-End Inspection</u> <u>Procedure</u>. For a complete listing of available related HUS Technical Publications, visit Hendrickson's Trailer Literature website at <u>www.Hendrickson-intl.com/TrailerLit</u>.

For any questions, contact Hendrickson Trailer Technical Services in the United States and Canada at 866-RIDEAIR (743-3247) or HTTS@Hendrickson-intl.com.

Call Hendrickson at 866.RIDEAIR (743.3247) for additional information.



**TRAILER COMMERCIAL VEHICLE SYSTEMS** 2070 Industrial Place SE Canton, OH 44707-2641 USA 866.RIDEAIR (743.3247) 330 489 0045 • Fax 800 696 4416

www.hendrickson-intl.com