H AVAILABLE LITERATURE TIRE INFLATION SYSTEMS TIREMAAX® PRO & CP

SUBJECT: Information and Requirements

LIT NO: T51005 DATE: November 2019



TIREMAAX® PRO

To assist with installation, operation, warranty, maintenance and other facets of your TIREMAAX[®] system, Hendrickson has made the following literature available on our website at:

www.Hendrickson-intl.com/TrailerLit

APPLICABLE LITERATURE

L583	Comprehensive Warranty Statement	<u>T19002</u>	Patent List
L878	TIREMAAX® Parts List	<u>T51002</u>	TIREMAAX [®] PRO & CP Installation, Service
L1256	TIREMAAX [®] Thermoplastic Tire Hose Poster		and Troubleshooting Procedures
T12007	General Safety Precautions and	T52001	TOOLBOX TIP: TIREMAAX [®] PRO PSI Setting
	Information for Technical Literature	<u>T52003</u>	TOOLBOX TIP: TIREMAAX [®] Hubcap Clocking

IMPORTANT: To ensure proper suspension safety, operation and performance, as well as warranty coverage, applicable installation and maintenance requirements must be followed.

For any questions on suspension literature or installation drawings, contact Hendrickson Trailer Technical Services, in the United States and Canada at 866-RIDEAIR (743-3247) or e-mail HTTS@Hendrickson-intl.com.

Actual product performance may vary depending upon vehicle configuration, operation, service and other factors.

Call Hendrickson at **866.RIDEAIR (743.3247)** for additional information.



TRAILER COMMERCIAL VEHICLE SYSTEMS 2070 Industrial Place SE Canton, OH 44707-2641 USA 866.RIDEAIR (743.3247) 330.489.0045 • Fax 800.696.4416 Hendrickson Canada 250 Chrysler Drive, Unit #3 Brampton, ON Canada L6S 6B6 800.668.5360 905.789.1030 • Fax 905.789.1033 Hendrickson Mexicana

Circuito El Marqués Sur #29 Parque Industrial El Marqués Pob. El Colorado, Municipio El Marqués, Querétaro, México C.P. 76246 +52 (442) 296.3600 • Fax +52 (442) 296.3601

www.hendrickson-intl.com

T51005 11-19 ECN 33032

© 2019 Hendrickson USA, LLC. All Rights Reserved. All trademarks shown are owned by Hendrickson USA, LLC., or one of its affiliates, in one or more countries. Information contained in this literature was accurate at the time of publication. Product changes may have been made after the copyright date that are not reflected.