⊞PARTS LIST

HT™ SERIES HT300YB SUSPENSIONS

LIT NO: L1271


DATE: September 2020 **REVISION**: A





Picture shown may not resemble all models.

HT300YB





ITEM	DESCRIPTION	PART NO.	QTY.	NOTE
1	BEAM ASSEMBLY			
	Standard, roadside, QUIK-ALIGN®	S-31377-3	1	
	Standard, curbside, QUIK-ALIGN	S-31377-4	1	
2	BUSHING ASSEMBLY	S-30862	2	
3	TUBE SLEEVE	S-7342	2	
4	ALIGNMENT COLLAR			
	4a Eccentric washer, QUIK-ALIGN	S-20925	2	Bolt hole is offset from center of collar
	4b Concentric washer, QUIK-ALIGN	S-20924	2	Pivot bolt hole is center of collar
5	BUSHING TUBE SPACER	S-21099	4	
6	QUIK-ALIGN PIVOT BOLT KIT	S-25948	2	Includes shear-type bolt, nut & washers
7	U-BOLT KIT, RD	S-3650/4	4	
8	TRI-FUNCTIONAL® II BUSHING KIT	S-26000	2	Includes bushing assembly, bushing tube spacers, bolt & nut
9	AIR SPRING PLATE			
	HT300YB.XXXX	S-23294	2	
	HT300YB-XX-XXX	A-24966	2	
10	AIR SPRING			
	HT300YB.XXXX	S-25319	2	
	HT300YB-XX-XXX	S-3830	2	
11	AIR SPRING BOLT KIT			
	HT300YB.XXXX	S-25339/2	2	
	HT300YB-XX-XXX	S-1981/2	2	
12	UPPER SHOCK CLEVIS			
	HT300YB.XXXX	S-20113	2	
	HT300YB-XX-XXX	S-2592	2	
13	SHOCK ABSORBER	S-20002	2	
14	SHOCK BOLT KIT	S-2157/2	2	
15	LOWER SHOCK CLEVIS (Not Shown)			
	Standard, roadside	S-20145-1	1	
	Standard, curbside	S-20145-2	1	
16	SHOCK STRAP KIT (Not Shown)			
	For A-20002 shock absorber	S-14587-1	1	

NOTE: US/YB can be identified by Dual Combo Stud A/S & YB "dot number" YB.XXX NOTE: UB/YB only consists of two part numbers HT300YB-7.5-001 or HT300YB-9-001

Actual product performance may vary depending upon vehicle configuration, operation, service and other factors.

All applications must comply with applicable Hendrickson specifications and must be approved by the respective vehicle manufacturer with the vehicle in its original, as-built configuration.

Contact Hendrickson for additional details regarding specifications, applications, capacities, and operation, service and maintenance instructions.

Call Hendrickson at 330.489.0045 or 866.RIDEAIR (743.3247) for additional information.



www.hendrickson-intl.com

TRAILER COMMERCIAL VEHICLE SYSTEMS 2070 Industrial Place SE Canton, OH 44707-2641 USA 866.RIDEAIR (743.3247) 330.489.0045 • Fax 800.696.4416 **Hendrickson Canada** 250 Chrysler Drive, Unit #3 Brampton, ON Canada L6S 6B6 800.668.5360 905.789.1030 • Fax 905.789.1033 Hendrickson Mexicana
Circuito El Marqués Sur #29
Parque Industrial El Marqués
Pob. El Colorado, Municipio El Marqués,
Querétaro, México C.P. 76246
+52 (442) 296.3600 • Fax +52 (442) 296.3601