## TIREMAAX® CP TIRE INFLATION SYSTEM

This TIREMAAX<sup>®</sup> CP controller assembly has been factory preset to:

## 90 psi

If the lamp remains on continuously for more than 10 minutes, one or more tires may be low or the system requires service.

Install the enclosure so drain hole is located on the bottom.

For complete service details, refer to Hendrickson publication L995, TIREMAAX CP Installation, Service and Troubleshooting Procedures, or call the Hendrickson technical service department at 800-455-0043 in the United States or 800-668-5360 in Canada.



L987 Rev A 12-08 ECN 17321 Printed in the United States of America



www.hendrickson-infl.com

Trailer Suspension Systems 250 Chrysler Drive, Unit #3 Brampton, ON Canada L6S 6B6 905.789.1030 Fax 905.789.1033

© 2008 Hendrickson USA, L.L.C. (U.S. Rights). All Rights Reserved