

PRODUCT UPDATE INTRAAX® ZMD® Air Spring Update

LIT NO: P26019

DATE: October 2019

Hendrickson Trailer Commercial Vehicle Systems announces a change to ZMD® ZERO MAINTENANCE DAMPING® air springs on INTRAAX® AANT 23K and AAT 23K suspensions.

Beginning early November 2019, a new, lightweight ZMD air spring will be standard on INTRAAX AANT 23K and AAT 23K suspension systems specified with ZMD. The new ZMD air spring saves 15 pounds per axle compared to the steel piston ZMD air spring.

The graphic below illustrates the visual differences between the new production ZMD air spring, C-39400 and current production ZMD air spring, C-35510.



New Production C-39400



Current Production C-35510



Note: Plastic Piston and Steel Piston ZMD air springs can be mixed.

Current INTRAAX model numbers will not change. However, aftermarket ZMD air spring part numbers will change. Refer to the appropriate INTRAAX parts list for specific replacement ZMD air spring part numbers.

To receive a valid model number, price and availability for an INTRAAX AANT 23K or AAT 23K suspension system equipped with ZMD technology, please submit L602 INTRAAX Ordering Guide to your customer service representative. Hendrickson's ZMD technology for INTRAAX can be requested by selecting ZMD in the shock absorber or air spring section of the INTRAAX Ordering Guide.

As always, Hendrickson is committed to providing world class products and customer service. Please contact your Hendrickson sales representative or call 1-866-RIDEAIR (743-3247) to speak with a customer service representative regarding this update.

Actual product performance may vary depending upon vehicle configuration, operation, service and other factors.

All applications must comply with applicable Hendrickson specifications and must be approved by the respective vehicle manufacturer with the vehicle in its original, as-built configuration. Contact Hendrickson for additional details regarding specifications, applications, capacities, and operation, service and maintenance instructions.

Call Hendrickson at 330.489.0045 or 866.RIDEAIR (743.3247) for additional information.



www.hendrickson-intl.com

TRAILER COMMERCIAL VEHICLE SYSTEMS

2070 Industrial Place SE
Canton, OH 44707-2641 USA
866.RIDEAIR (743.3247)
330.489.0045 • Fax 800.696.4416

Hendrickson Canada

250 Chrysler Drive, Unit #3
Brampton, ON Canada L6S 6B6
800.668.5360
905.789.1030 • Fax 905.789.1033

Hendrickson Mexicana

Circuito El Marqués Sur #29
Parque Industrial El Marqués
Pob. El Colorado, Municipio El Marqués,
Querétaro, México C.P. 76246
+52 (442) 296.3600 • Fax +52 (442) 296.3601