

PRODUCT UPDATE

TIREMAAX® Tire Hoses

LIT NO: P56066

DATE: September 2021

Hendrickson Trailer Commercial Vehicle Systems announces a change to aftermarket stainless steel tire hose availability for TIREMAAX® tire inflation systems. Beginning January 1, 2022, Hendrickson will **no longer offer** stainless steel tire hoses (VS-31503-# / VS-31504-#) designed to work with the hubcap-mounted rotary union. Thermoplastic tire hoses (VS-33767-# / VS-33769-#) will be the only version available for use with current production hubcaps.

The cross-reference table shows the thermoplastic part number to be used in place of the stainless steel.

HOSE STYLE	WHEEL STYLE	TIRE SIZE	WHEEL MATERIAL	POSITION	FITTING	STAINLESS STEEL PART NUMBER	REPLACED BY →	THERMOPLASTIC PART NUMBER
Standard	Dual	17.5"	Steel, Aluminum or Combo	Inner	Straight	VS-31503-2		
				Outer	180-Degree	VS-31504-1	VS-33769-3	
		19.5"	Aluminum	Inner	Straight	VS-31503-2	VS-33767-4	
				Outer	180-Degree	VS-31504-1	VS-33769-1	
			Steel or Combo	Inner	Straight	VS-31503-2	VS-33767-2	
				Outer	180-Degree	VS-31504-1	VS-33769-3	
		22.5"	Aluminum	Inner	Straight	VS-31503-2	VS-33767-5	
				Outer	180-Degree	VS-31504-1	VS-33769-1	
			Steel or Combo	Inner	Straight	VS-31503-1	VS-33767-1	
				Outer	180-Degree	VS-31504-2	VS-33769-1	
		24.5"	Aluminum	Inner	Straight	VS-31503-1	VS-33767-2	
				Outer	180-Degree	VS-31504-2	VS-33769-2	
	Steel or Combo		Inner	Straight	VS-31503-1	VS-33767-1		
			Outer	180-Degree	VS-31504-2	VS-33769-1		
	Super Single	22.5"	Aluminum	N/A	Straight	VS-31503-3	VS-33767-3	
			Steel	Inboard Stem	Straight	VS-31503-3	VS-33767-3	
		Outboard Stem		180-Degree	VS-31504-1	VS-33769-1		

Note that the aftermarket stainless steel tire hoses (VS-29003-# / VS-29004-#) designed to interface with the original TIREMAAX spindle-mounted rotary union will remain available for sale.

As always, Hendrickson is committed to providing world class products and customer service. Please contact your Hendrickson sales representative or call 1-866-RIDEAIR (743-3247) to speak with a customer service representative regarding this update.

*Actual product performance may vary depending upon vehicle configuration, operation, service and other factors.
All applications must comply with applicable Hendrickson specifications and must be approved by the respective vehicle manufacturer with the vehicle in its original, as-built configuration.
Contact Hendrickson for additional details regarding specifications, applications, capacities, and operation, service and maintenance instructions.*

Call Hendrickson at 330.489.0045 or 866.RIDEAIR (743.3247) for additional information.



www.hendrickson-intl.com

TRAILER COMMERCIAL VEHICLE SYSTEMS
2070 Industrial Place SE
Canton, OH 44707-2641 USA
866.RIDEAIR (743.3247)
330.489.0045 • Fax 800.696.4416

Hendrickson Canada
250 Chrysler Drive, Unit #3
Brampton, ON Canada L6S 6B6
800.668.5360
905.789.1030 • Fax 905.789.1033

Hendrickson Mexicana
Circuito El Marqués Sur #29
Parque Industrial El Marqués
Pob. El Colorado, Municipio El Marqués,
Querétaro, México C.P. 76246
+52 (442) 296.3600 • Fax +52 (442) 296.3601