HPARTS LIST


OPTIMAAX® Liftable Forward Tandem Axle and Suspension System for Freightliner Vehicles

LIT NO: SP-309


DATE: October 2018 **REVISION**: A

CONTENTS

DESCRIPTION	PAGE
Parts List	2
Special Tools	4







2 SP-309



OPTIMAAX® for Freightliner Vehicles

Trame Hanger 1	QTY.
79651-001	Spring Washer 2
79651-002 Right Hand 1 2 80100-001 Cross Member 1 3 34013-287 Lift Air Spring Set	r Spring Washer 2 r Ride Air Spring Locknut 2
2 80100-001 Cross Member 1 3 **M16 Huck Bolt 4 4 4 4 4 4 4 4 4	1 0
3 **M16 Huck Bolt 4 18 *Lift Air Spring 4 **M16 Huck Locknut 4 19 58035-001 %"-16 UNF x 1" Lift Air Spring QUIK-ALIGN Service Kit, Includes Key Nos. 5-10	
4 **M16 Huck Locknut 4 19 58035-001 %"-16 UNF x 1" Lir QUIK-ALIGN Service Kit, Includes Key Nos. 5-10 20 17497-005 %" Lift Air Spring \$	2
QUIK-ALIGN Service Kit, Includes Key Nos. 5-10 20 17497-005 %" Lift Air Spring S	
60632-042 Axie Set 21 17700-031 3/4"Locknut	
	2
	sorber Service Kit, Includes
34013-281 QUIK-ALIGN Collar Service Kit, One Side Key Nos. 22-28	
Includes Key Nos. 5-9 22 80335-001 Shock Absorber	2
5 *QUIK-ALIGN Eccentric Collar 2 2 78250-003 Upper Shock Brac	cket 2
6 *QUIK-ALIGN Concentric Collar 2 24 50764-019 3/"-10 UNC x 41/2"	cket 2 "Upper Shock Bolt 2
	r Shock Flange Locknut 2
	"Lower Shock Bolt 2
7 *Shear Round Head Bolt 2 27 22962-004 %" Lower Shock V	Washer 4 Locknut 2
8 *7/s" Hardened Steel Washer 4 28 47764-000 5/s" Lower Shock L	Locknut 2
9 *7%" Prevailing Torque Heavy Hex Nut 2 *****S-cam Servic	
TRI-FUNCTIONAL® III Bushing Service Kit 60961-864 Includes Key No	os. 29-32
34013-283 Axie Set , Includes Key Nos. 10, 12, 36 60961-869 Fasteners Only,	Includes Key Nos. 30-32
34013-284 One Side, Includes Key Nos. 10, 12, 36 29 S-cam Bracket	
34013-285 One Side , Includes Key Nos. 7-9, 12, 36 80023-001 Left Hand	1
34013-286 Thrust Washer Service Kit, One Side 80023-002 Right Hand	1
10 *Thrust Washer 4 30 64202-000 5/16"-18 UNC x 31/4 11 79357-004 Axle Beam Assembly, Includes Key No. 12 1 31 75952-000 5/16"-18 UNC Flance	
11 79357-004 Axle Beam Assembly, Includes Key No. 12 1 31 75952-000 5/16"-18 UNC Flang	ge Nut 8
75.5 Wide Track, 33.4" Frame Width 32 75953-001 5/6"-18 UNC x 1" F	
	Controller Module, Includes
34013-237 Axle Stop Service Kit, Axle Set Key Nos. 33-34	
	J (Contact OEM for Part No.) 1
Axle Stop 34 80860-000 ***Splash Shield A	Assembly 1
	Controller Manifold 1
<u>14 79887-002 Right Hand 1</u> 36 H Rubber Assemb	oly Oil 1 per Bushing
15 79191-004 Ride Air Spring 2	
49177-006 Ride Air Spring Fasteners Service Kit, Axle Set Includes Key Nos. 16-17	

NOTE: * Item included in assembly / kit only, part not sold separately.

SP-309 3

^{**} Item required, component supplied by vehicle manufacturer. Hendrickson is not responsible for components not supplied by Hendrickson, for assistance with maintenance and rebuild instructions on these components see vehicle manufacturer.

^{***} Not shown, refer to Hendrickson Literature No.17730-310 for more information.

^{****} Required for vehicles equipped with drum brakes only.



■ Special Tools

TRI-FUNCTIONAL® III BUSHING TOOL

Hendrickson Part No. 66086-122

Use with 35%" wide bushings



SHEAR HEAD BOLT-E20 1" SOCKET TOOL

Hendrickson Part No. A-24536

For Service



This is a general parts list to provide directional information. Components may vary by model. Questions in regards to parts, contact Hendrickson Truck Parts at 1.866.755.5968 (Toll-free U.S. and Canada), 1.630.910.2800 (Outside U.S. and Canada) or e-mail: truckparts@hendrickson-intl.com.

www.hendrickson-intl.com -



Truck Commercial Vehicle Systems 800 South Frontage Road Woodridge, IL 60517-4904 USA 1.866.755.5968 (Toll-free U.S. and Canada) 1.630.910.2800 (Outside U.S. and Canada) Fax 1.630.910.2899