# **H**AERO CLAD<sup>®</sup> Bumper

# AERO CLAD<sup>®</sup> for Volvo VNL

Hendrickson **AERO CLAD**<sup>®</sup> bumpers for New Volvo VNL tractors offer a bright mirrored finish that is both lightweight and durable. Unlike traditional chrome or painted bumpers, AERO CLAD bumpers resist corrosion, cracking, pitting, peeling and fading. In addition, AERO CLAD bumpers offer greater ground clearance compared to the OEM plastic option to help reduce maintenance due to high curbs, snow drifts or uneven inclines. Backed by a 5-year warranty\*, AERO CLAD bumpers offer the quality and reliability that customers have come to expect from Hendrickson.

\* Contact your local Hendrickson representative for complete warranty terms, conditions and limitations.







To learn more about AERO CLAD, call 815.727.4031 or visit www.hendricksonbumper.com



## **AERO CLAD®** Features and Benefits

- Lightweight to help enhance fuel efficiency
- · Easy installation to factory mounts
- Durable, bright mirrored finish
- Finish 10 times thicker than chrome

- Resists corrosion, cracking, pitting, peeling and fading
- Quality, American made product
- Minor abrasions can be buffed
- Full 5-year limited warranty\*

\* Contact your local Hendrickson representative for complete warranty terms, conditions and limitations.

#### Part Numbers

PART NO.	MATERIAL / FINISH	GAUGE / THICKNESS	STYLE <sup>1</sup>	LIGHT	CENTER STEP	VENT	тоw	RADAR COMPATIBLE <sup>2</sup>	YEAR	MOUNT / BRACKET REQUIRED <sup>3</sup>	LICENSE PLATE HOLES
84743726	AERO CLAD	0.125 in.	LWO Closed End	Ν	N	Y	Y	Y	2018 +	Y	Y
84743727	AERO CLAD	0.125 in.	SWO Closed End	Ν	N	Y	Y	Y	2018 +	Y	Y
84743728	AERO CLAD	0.125 in.	LWO Closed End	2 lights	N	Y	Y	Y	2018 +	Y	Y
84743729	AERO CLAD	0.125 in.	SWO Closed End	2 lights	N	Y	Y	Y	2018 +	Y	Y
84743730	AERO CLAD	0.125 in.	LWO Closed End	4 lights	N	Y	Y	Y	2018 +	Y	Y
84743731	AERO CLAD	0.125 in.	SWO Closed End	4 lights	N	Y	Y	Y	2018 +	Y	Y

1. Standard Wheel Opening (SWO) / Large Wheel Opening (LWO)

2. Radar compatible: unit is mounted off the cross member behind the bumper

3. Supplied with mounting brackets installed on bumper

## **Product Information**



Actual product performance may vary depending upon vehicle configuration, operation, service and other factors.

All applications must comply with applicable Hendrickson specifications and must be approved by the respective vehicle manufacturer with the vehicle in its original, as-built configuration. Contact Hendrickson for additional details regarding specifications, applications, capacities, and operation, service and maintenance instructions.

#### Call Hendrickson at 815.727.4031 for additional information.



SPECIALTY PRODUCTS - BUMPER AND TRIM 501 Caton Farm Road Lockport, IL 60441 USA 815.727.4031 hbatcustservice@hendrickson-intl.com

www.hendrickson-intl.com

C198 12-20

© 2019 - 2020 Hendrickson USA, LLC. All Rights Reserved. All trademarks shown are owned by Hendrickson USA, LLC., or one of its affiliates, in one or more countries, except for Volvo and VNL, which are owned by Volvo Group North America, LLC or one of its affiliates. Information contained in this literature was accurate at the time of publication. Product changes may have been made after the copyright date that are not reflected. Printed in United States of America