

H AVAILABLE LITERATURE


TRAILER SUSPENSION SYSTEMS INTRAAX® AND CONNEX®

SUBJECT: Fixed Suspension Installation
Information and Requirements

LIT NO: L1073

DATE: September 2019

REVISION: L



To assist with installation, welding, warranty, maintenance and other facets of your fixed suspension, the following Hendrickson literature and installation drawings are available on our website at:

www.Hendrickson-intl.com/TrailerLit

APPLICABLE LITERATURE

<u>B31</u>	<i>Torque Specifications</i>
<u>L64</u>	<i>Welding Procedures</i>
<u>L388</u>	<i>Ride Height Settings</i>
<u>L459</u>	<i>Checking Trailer Ride Height</i>
<u>L578</u>	<i>Suspension Preventive Maintenance Guide</i>
<u>L579</u>	<i>Alignment Procedures</i>
<u>L583</u>	<i>Comprehensive Warranty Statement</i>
<u>L635</u>	<i>INTRAAX® Shock Mount Assembly Procedure</i>
<u>L707</u>	<i>Suspension Application Guide</i>
<u>L839</u>	<i>Reapplying Axle Sealant Procedure</i>
<u>L974</u>	<i>Drum Brake Maintenance Procedures</i>
<u>L1072</u>	<i>QUIK-ALIGN® Pivot Connection Fastener Information</i>
<u>T12007</u>	<i>General Safety Precautions and Information for Technical Literature</i>
<u>T19002</u>	<i>Patent List (available online at www.hendrickson-intl.com/patent)</i>

OPTIONS

<u>L496</u>	<i>Standard Wheel-end Maintenance</i>
<u>L668</u>	<i>Non-delay HCV Installation</i>
<u>L715</u>	<i>SURELOK® Installation Procedures</i>
<u>L1115</u>	<i>Aftermarket HCV VS-228 Replacement</i>
<u>T12004</u>	<i>Softcoat/Hot Wax Maintenance Procedures</i>
<u>T51002</u>	<i>TIREMAAX® CP & PRO Installation, Service and Troubleshooting Procedures</i>
<u>T71004</u>	<i>ADB HUB and Rotor Assembly, Caliper Mounting</i>
<u>T72002</u>	<i>HXL7® Wheel-end Maintenance</i>
<u>T72006</u>	<i>HXL3® Wheel-end Maintenance</i>
<u>T72007</u>	<i>HXL5® Wheel-end Maintenance</i>
<u>T72009</u>	<i>MAXX22T® ADB Installation and Maintenance (for other ADB maintenance procedures, refer to the brake caliper manufacturer)</i>
<u>T82006</u>	<i>Stud Replacement Procedures</i>
<u>T91001</u>	<i>UBL Information and Requirements</i>

Continued on back...

INTRAAX® INSTALLATION DRAWING MATRIX

SUSPENSION MODEL	RATING	5 INCH AXLE	LDA 5.75 INCH AXLE	BOLT-ON WINGLESS SIDE MOUNT	DROP FRAME VAN	ARL KIT				ADDITIONAL DRAWINGS		
						ADJUSTABLE BRACKET	CLEVIS & FLAT BRACKET	FLAT BRACKET	"L" BRACKET	FRAME REQUIREMENTS	MOUNTING HOLE PATTERNS	COMMON COMPONENTS
AAT	23/25/30K	D-25302	D-30815				D-24132		D-24131	D-29431	D-26651	D-25266
AAL	23/25/30K	D-25153	D-30900			D-26595						
AANT	23K		D-28108	D-27367			D-28542		D-28541			
AANL	23K		D-29460									
AAEDT	30K	D-25321						D-26596				
AAEDL	30K	D-25153				D-26595						
AANLS	20K	D-26136			D-27619							

CONNEX™ INSTALLATION DRAWING MATRIX

MODEL	RATING	INSTALLATION DRAWING	COMMENTS
CXU	23/25K	D-38070	
		C-24644	High flow HCV Kit
CXY	23/25K	D-38979	

IMPORTANT: To ensure proper suspension safety, operation and performance, as well as warranty coverage, the above applicable installation and maintenance requirements must be followed.

For any questions on suspension literature or installation drawings, contact **Hendrickson Trailer Technical Services**, in the United States and Canada at 866-RIDEAIR (743-3247) or e-mail HTTS@Hendrickson-intl.com.

Actual product performance may vary depending upon vehicle configuration, operation, service and other factors.

Call Hendrickson at **866.RIDEAIR (743.3247)** for additional information.



www.hendrickson-intl.com

TRAILER COMMERCIAL VEHICLE SYSTEMS

2070 Industrial Place SE
Canton, OH 44707-2641 USA
866.RIDEAIR (743.3247)
330.489.0045 • Fax 800.696.4416

Hendrickson Canada

250 Chrysler Drive, Unit #3
Brampton, ON Canada L6S 6B6
800.668.5360
905.789.1030 • Fax 905.789.1033

Hendrickson Mexicana

Circuito El Marqués Sur #29
Parque Industrial El Marqués
Pob. El Colorado, Municipio El Marqués,
Querétaro, México C.P. 76246
+52 (442) 296.3600 • Fax +52 (442) 296.3601

L1073 Rev L 09-19 ECN 32494 Rev K 06-17 ECN 30191 Rev J 06-16 ECN 25275 Rev H 03-16 ECN 24915 Rev G 03-15 ECN 24032

© 2008 - 2019 Hendrickson USA, L.L.C. All Rights Reserved. All trademarks shown are owned by Hendrickson USA, L.L.C., or one of its affiliates, in one or more countries.

Information contained in this literature was accurate at the time of publication. Product changes may have been made after the copyright date that are not reflected.

Printed in United States of America