HAVAILABLE LITERATURE TRAILER SUSPENSION SYSTEMS HT^M SERIES SUSPENSIONS

SUBJECT: Fixed Suspension Installation Information and Requirements

LIT NO: T44004 DATE: September 2019



To assist with installation, welding, warranty, maintenance and other facets of your fixed suspension, the following Hendrickson literature and installation drawings are available on our website at:

www.Hendrickson-intl.com/TrailerLit

APPLICABLE LITERATURE

- <u>B31</u> Torque Specifications
- L64 Welding Procedures
- L388 Ride Height Settings
- L459 Checking Trailer Ride Height
- L577 HT[™] Suspension Installation Procedures
- L578 Suspension Preventive Maintenance Guide
- L579 Alignment Procedures
- L583 Comprehensive Warranty Statement
- L707 Suspension Application Guide
- L1072 QUIK-ALIGN[®] Pivot Connection Fastener Information
- <u>T12007</u> General Safety Precautions and Information for Technical Literature
- <u>T19002</u> *Patent List* (available online at www.hendrickson-intl.com/patent)

OPTIONS

- L668Non-delay HCV InstallationL1115Aftermarket HCV VS-228 Replacement
- L1182 Controls Parts Catalog
- <u>T91001</u> UBL Information and Requirements

Continued on back...



HT™ SERIES INSTALLATION DRAWING MATRIX

MODEL ¹	INSTALLATION DRAWING	COMMENTS
HT190T	By Model²	Includes TA & TB model suffixes
HT190U		Includes UB model suffixes
HT230		Includes TA, TB & TC model suffixes
HT250T		
HT250U		Includes UB model suffixes
HT250US	D-25773	
HT250Y	By Model ²	
HT250YS	D-31943	
HT250YB	D-30887	
HT300	By Model ²	Includes TA & TB model suffixes
HT300U	By Model ²	Includes UB model suffixes
HT300US	D-33039	
HT300YB	D-31384	For use with HT300U only ^{3}
	D-35072	For use with HT300US only $\frac{3}{2}$
Additional Notes:		

¹ Contact Hendrickson for Additional models not listed.

² Contact Hendrickson for the installation drawing for the specific suspension model number.

³ Applies to Y-beam suspensions used with other HT Series Suspension models. Refer to L707 Application Guide for details.

IMPORTANT: To ensure proper suspension safety, operation and performance, as well as warranty coverage, the above applicable installation and maintenance requirements must be followed.

For any questions on suspension literature or installation drawings, contact Hendrickson Trailer Technical Services, in the United States and Canada at 866-RIDEAIR (743-3247) or e-mail HTTS@Hendrickson-intl.com.

Actual product performance may vary depending upon vehicle configuration, operation, service and other factors.

Call Hendrickson at 866.RIDEAIR (743.3247) for additional information.



 TRAILER COMMERCIAL VEHICLE SYSTEMS

 2070 Industrial Place SE

 Canton, OH 44707-2641 USA

 866.RIDEAIR (743.3247)

 30.489.0045 • Fax 800.696.4416

 Hendrickson Canada

 250 Chrysler Drive, Unit #3

 Brampton, ON Canada L6S 6B6

 800.668.5360

 905.789.1030 • Fax 905.789.1033

Hendrickson Mexicana

Circuito El Marqués Sur #29 Parque Industrial El Marqués Pob. El Colorado, Municipio El Marqués, Querétaro, México C.P. 76246 +52 (442) 296.3600 • Fax +52 (442) 296.3601

T44004 09-19 ECN 32494

© 2019 Hendrickson USA, LLC. All Rights Reserved. All trademarks shown are owned by Hendrickson USA, LLC., or one of its affiliates, in one or more countries. Information contained in this literature was accurate at the time of publication. Product changes may have been made after the copyright date that are not reflected.